



MULTIFUNCTION CONCENTRATOR INDICATOR

LATEX FREE | CE MARK

The PRO2 Check® Elite Device is used to verify the oxygen concentration, the output pressure, and the output flow from an oxygen concentrator. It may also be utilized to spot check other gaseous or liquid oxygen systems.

FEATURES

- Measures oxygen, pressure and flow
- Accurate O2 % (within +/- 2%)
- Durability
- Portable
- Easy one-time calibration
- Belt clip carrying case and strap
- Compatible with all oxygen concentrators

INCLUDED COMPONENTS



CARRYING CASE AND STRAP



2 FOOT TUBING

PRO₂ CHECK ELITE

ITEM	DESCRIPTION	PK
PRO2ELITE-1	PRO2 Check Elite Multifunction Concentrator Indicator	1



Video Overview



Calibration Video

Used to measure the outlet pressure of an oxygen concentrator

Used to measure oxygen flows and oxygen concentrations, and verify and calibrate oxygen concentrator values



Pressure Mode:
 Range: 0 to 25 PSIG (0 to 172 kPa)
 Resolution: 0.1 PSIG (.1 up to 99.9 kPa;
 1.0 over 100 kPa)
 Accuracy: ± 1% of Full Scale

Flow Mode:
 Range: 0 to 10 LPM
 Resolution: 0.1 LPM

LIT-10156 Rev.1